


STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple Suite 1210 Box 145801

Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	Genera	al Information			
	1.	Report Time Period: From (mo./yr.)			
	2.	DOGM File Number (Mine No): M /027 / 006			
	3.	Mine Name: Continental Lime Inc Cricket Mtn. Quarry			
	4.	Mineral(s) Mined (or permitted to mine): Limestone			
	5.	Type of mine ☐ Surface Mine or ☐ Underground Mine			
	6.	Legal Description (Location of Lands Affected):			
		NW 1/4,1/4,1/4, Section 36 , Township 215 , Range 10W			
		SW 1/4, SE 1/4, 1/4, Section 25, Township 215, Range 10W			
		1/4,1/4,1/4, Section, Township, Range			
7.	Name of Operator or Company: Continental Lime Inc.				
	8.	Permanent Street Address: 3950 South 700 East, Suite 301			
		City, State, Zip: Salt Lake City, Utah 84107			
		Phone: (801) 264-6876			
	9.	Company Representative (or designated operator):			
		Name: Joe Brokke			
		Title: Plant Manager			
		Business Address: P.O. Box 669			
		City, State, Zip: Delta, Utah 84624			
		Phone: (435) 864-3823			
		☐ Please check if any of the above information has changed since previous year.			
II.	Mining	and Reclamation			
	1.	Was the mine active during the past year? Yes ☒ No ☐			
	2.	If active, how much ore or mineral was mined?1,224,600 tons			
	3.	If inactive, what year was the mine last active?n/a			

		3.	How much additional acreage was disturbed during the past year?13
		4.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Mining and wastedumping occurred in previously
			disturbed areas. Construction of the haul road to the
			west quarry area disturbed approximately 13 acres.
	5.		How much acreage was reclaimed during the past year?0
	6.		Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. Approximately 1/2 of the wastedump area was sloped to
			3:1 and covered with fines in preparation for topsoil and seed applications.
	7.		What is the total disturbed acreage at years end?
	8.		Briefly summarize any mining and/or reclamation plans for the upcoming year. Mining in section 36 to the 5740 elevation;
			Completion of the haul road to the west area and
			development of a mining face in the west area. Completion
			of waste dump sloping, topsoiling and seeding.
			Interin reclamation of catch benches.
NO	TE:		Section III., "Additional Information" applies only to large mining operations.
III.	Addition	ial I	Information
	1.		An updated surface facilities map should be attached if there have been significant changes since the previous was submitted.
	2.		Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.
IV.	Signati	ure	Requirement
	I he	erel	by certify that the foregoing is true and correct.
			Name (Typed or Print):
			Title of Operator: Plant Manager
			Signature of Operator:
			Date: